

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | 1. Name of the Officer | Sivaprasad C.S | | | | | | |
|---|--|------------------|------|----------------------|------|-----------------------|------|
| 2. Name of the School | Santa Maria Public School, ^{Ranni} Patharamthitta | | | | | | |
| 3. Location with name of Education District/ Sub. District | Mannamamthya | | | | | | |
| 4. Classification of Building as specified in column 4 of the application for fitness certificate and size. | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px dotted black;">Size with Height</th> <th style="text-align: left; border-bottom: 1px dotted black;">Year</th> </tr> </thead> <tbody> <tr> <td style="border-bottom: 1px dotted black;">1. 3055 X 851 X 7.84</td> <td style="border-bottom: 1px dotted black;">1916</td> </tr> <tr> <td style="border-bottom: 1px dotted black;">2. 2788 X 2608 X 7.84</td> <td style="border-bottom: 1px dotted black;">1930</td> </tr> </tbody> </table> | Size with Height | Year | 1. 3055 X 851 X 7.84 | 1916 | 2. 2788 X 2608 X 7.84 | 1930 |
| Size with Height | Year | | | | | | |
| 1. 3055 X 851 X 7.84 | 1916 | | | | | | |
| 2. 2788 X 2608 X 7.84 | 1930 | | | | | | |
| 5. Period for which the certificate is issued | 2020-2021 | | | | | | |
| 6. Nature of defects , if any | <div style="font-size: 4em; line-height: 1;">}</div> Nil | | | | | | |
| a) Foundation and basement | | | | | | | |
| b) Superstructure | | | | | | | |
| c) Doors and Windows | | | | | | | |
| d) Wood work wrought and put up | | | | | | | |
| e) Roof | | | | | | | |
| f) Flooring | | | | | | | |
| g) Miscellaneous (Cracks, etc.) | | | | | | | |
| 7. Any major defects noticed which will render the building unsafe in any manner | NO | | | | | | |
| 8. Whether maintenance works have been done properly | Yes | | | | | | |
| 9. Whether the structure is sound or not for conducting classes | Sound for conducting classes under normal weather con. | | | | | | |

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 29-12-2020 and found to be fit / unfit to conduct classes, for the period 2020-21 for the reasons stated above.

Place : Ranni

Date : 29-12-20

(Seal)

ASSISTANT ENGINEER
LEGD. (PUBLIC WORKS) SECTION
RANNI PAZHAVANGADI
RANNI
 Assistant Engineer

Self Attested

For Santa Maria Public School

Manager

Thomas

THOMAS JOHN
PRINCIPAL
SANTA MARIA PUBLIC SCHOOL
SCHOOL CODE: 75479
MAKKAPUZHA P.O., RANNI
PATHANAMTHITTA, KERALA - 689 676
santamariapsranni@gmail.com